

Alkon Corporation.
CNC / LATHE Preventive Maintenance Instructions

For Machine Numbers: 1306, 1308, 1309, 1311, 1312, 1313, 1314, 1315, 1336 & 1337

MONTHLY TASKS TO BE COMPLETED

LUBRICATION

- CHECK LUBE OIL LEVELS

ELECTRICAL

- CHECK ALL SAFETY RELATED SWITCHES FOR PROPER FUNCTION

MACHINE CARE

- VISUALLY CHECK FOR LOOSE OR MISSING COVERS
- CHECK FOR ANY ABNORMALITIES ON OPERATORS CONTROL PANEL

QUARTERLY TASKS TO BE COMPLETED

MECHANICAL

- CHECK COOLANT TANK FOR BUILD UP