

Alkon Corporation.
Bridgeport Mill Preventive Maintenance Instructions

For Machine Numbers: 1902

ANNUAL TASKS TO BE COMPLETED

MACHINE CARE

- CHECK LUBRICATION POINTS FOR PROPER LEVEL
- CHECK HARDWARE FOR TIGHTNESS
- VISUALLY INSPECT GEAR & SHAFTS FOR WEAR / DETERIORATION
- VISUALLY INSPECT GEARS AND SHAFTS FOR RUST / CORROSION
- CHECK BELTS & PULLYS FOR WEAR
- CHECK BELTS FOR PROPER TENSION